



Township of Hillsborough

COUNTY OF SOMERSET
THE PETER J. BIONDI BUILDING
379 SOUTH BRANCH ROAD
HILLSBOROUGH, NJ 08844
(908) 369-4313
www.hillsboroughnj.gov

The Breakdown for RTU or HVAC Installation

Each Subcode Official and/or Inspector has specific Code responsibilities as follows:

- Building reviews and inspects the attachment of the appliance to structure and the associated duct work.
- Electric reviews and inspects over current protection and connection to existing power.
- Plumbing reviews and inspects the gas line and condensate line.
- Fire reviews and inspects the appliance and the installation per manufacturer's specifications. The cost of the equipment should be on the Fire card. (Fire also looks at duct detectors when required)

Each Subcode Technical Section should reflect this work in the "Description of Work" sections and the estimated cost for each (labor and materials) should be shown on the corresponding Technicals.